


Abandoned Service Lines off of Inserted Mains



Prioritization of Approximately 700 Abandoned Service Lines

- **Columbia researched:**
 - Location of meter set prior to abandonment
 - Installation method of new service line
 - Service line retirement documentation
- **Prioritization of field verification*:**
 - First Tier: 202
 - Inside meter set (A), and
 - Open cut installation (B), and
 - Service line retirement documentation not included in records
 - Second Tier: 119
 - Inside meter set (A), and
 - Plastic insert (D) or tie-over (C), and
 - Service line retirement documentation not included in records
 - Third Tier: 381
 - Outside meter, or
 - Service line retirement documentation included in records
- **Completion Goal November 16, 2019**
- **Based on the results of the prioritized service line inspections, further action and prioritization will be determined on the remaining services on the abandoned mains**

*Numbers between Tiers subject to change as review continues